



#16 Yellowknife Airport
Yellowknife, NWT
X1A 3T2

Your file Votre référence

May 14th; 2010

Our file Notre référence

Ron Breadmore
Department of Indian Affairs and Northern Development
Box 1500
YELLOWKNIFE, NT X1A 3R2

**Re: Land Use Permit W2009X0002
 Site Remediation
 North Inca Advanced Exploration Site Remediation, NT**

Dear Mr. Breadmore,

An inspection of the North Inca advanced exploration site remediation project was conducted on May 13th, 2010 by Resource Management Officers Clint Ambrose and Nahum Lee. The inspection was carried out to ensure operating conditions annexed to the above noted land use permit were adhered to during this operation.

The remediation of the land use area appeared to be complete and the only remaining items on site were two signs, some miscellaneous lumber at the waste storage area and the dozer at the north end of the peninsula. No concerns were noted during the inspection, and once the lumber, signs and dozer are removed, the Permittee must notify the Inspector. Your copy of the Environmental Inspection Report is enclosed and should be self explanatory.

If you have any questions or concerns, please contact Mr. Nahum Lee at (867) 669-2757 or the undersigned at (867) 669-2794.

Yours truly,

Clint Ambrose
Resource Management Officer III
South Mackenzie District
Indian and Northern Affairs Canada

cc: WLWB



ENVIRONMENTAL INSPECTION REPORT

Permittee:	INAC- CARD	Inspection Date – May 13 th , 2010
------------	------------	---

	Permit Expiry Date	Last Previous Inspection
Land Use Permit No.	W2009X0002	March 18 th , 2014
Quarrying Permit No.		August 6 th , 2009
Contractor:	Tli Cho Logistics/AEL	Subcontractor:

Location(s) Inspected:	North Inca Advanced Exploration Site, Inca Peninsula, Indin Lake, NT
------------------------	--

Current Stage of Operation:	Removal of waste to the Old Colomac Mine Site occurred this winter and there was no activity at the time of the inspection.
-----------------------------	---

Program Modifications Approved:	
---------------------------------	--

Condition of Operation A - Acceptable U - Unacceptable N/A - Not Applicable

#	Operating Condition	Aspect Inspected			Condition
		North Inca Site			
A	Location and Area	A			
B	Time	A			
C	Type and Size of Equipment	A			
D	Methods and Techniques	A			
E	Type, Location, Capacity and Operation of All Facilities	A			
F	Control or Prevention of Ponding of Water, Flooding, Erosion, Slides and Subsidence of Land	A			
G	Use, Storage, Handling and Ultimate Disposal of Any Chemical or Toxic Material	A			
H	Wildlife and Fisheries Habitat	A			
I	Storage, Handling and Disposal of Refuse or Sewage	A			
J	Protection of Historical, Archeological and Burial Sites	A			
K	Objects and Places of Recreational, Scenic or Ecological Value	N/A			
L	Security Deposit	N/A			
M	Fuel Storage	A			
N	Methods and Techniques for Debris and Brush Disposal	A			
O	Restoration of the Lands	A			
P	Display of Permits and Permit Numbers	A			
Q	Matters Not Inconsistent With the Regulations	N/A			
R	Sections 8 to 16 M.V.L.U.R.	A			

ENVIRONMENTAL INSPECTION REPORT Pg. 2
(Continued)

Date: May 13 th , 2010	Permit #: W2009X0002
-----------------------------------	----------------------

Explanatory Remarks
<p>An inspection of the North Inca remediation project was conducted on May 13th, 2010 by Resource Management Officers Clint Ambrose and Nahum Lee. The inspection was carried out to ensure operating conditions annexed to the above noted land use permit were adhered to during this operation.</p> <p>There was no activity at the time of the inspection, and it appeared as though the land use area remediation that was proposed in Remedial Action Plan has been completed. The temporary camp and the equipment to conduct the remediation has been demobilized and the only items remaining were 2 signs, a small amount of miscellaneous lumber at the waste storage area and a dozer at the north end of the peninsula.</p> <p>It is the Inspector's understanding that the Permittee still intends on removing the dozer along the winter road, and once this piece of equipment, signs and miscellaneous lumber has been removed from the land use area the Inspector must be notified.</p>

Completed off Site
Representative's Signature

Clint Ambrose
Inspector


Inspector's Signature



W2009X0002 - North Inca - Indin Lake
Looking north at the land use area where the mine infrastructure has been removed and the camp was set up.



W2009X0002 - North Inca - Indin Lake
Looking southwest at the land use area.



W2009X0002 - North Inca - Indin Lake
Bagged waste was stored here last summer for removal to the Old Colomac Mine Site for disposal.



W2009X0002 - North Inca - Indin Lake
Small dozer at the north end of the peninsula that will be removed from the land use area.